


Handling Precautions

Soldering (For only reflow soldering)

1. Recommended P.C. Board pattern (Unit: mm) Please use both side of P.C.B.




2. General cautions for soldering

For soldering, please perform a temperature pattern of the right note for reference.


Please do not perform heating more than 260 degrees Celsius 10seconds.

I received the internal joining, but I melt, and such as a short circuit, opening, a gap of a case may occur.

This part is the lead-free correspondence kind that I received.



■Taping



■Packaging Quantity

Туре	Package quantity
Taping quantity	1,000pcs / reel